

Professional Food Equipment Co

SERVICE REPORT

Work Order: WO-689823 | Date: 07/25/2025

Client Information

Client	Mercer PLC
Address	583 Jones Falls, Amytown, AZ 89843
Phone	533-934-1095

Equipment Information

Field	Value
Machine Type	Fryers
Model	CrispKing 300
Serial Number	SN42988726

Service Details

Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

Technician Information

Technician Name	David Chen
Technician ID	TECH-012
Certification	EPA Type I/II Certified
Arrival Time	11:28
Labor Hours	2.98

Technician Signature: _____ **Date:** _____

Professional Food Equipment Co | 24/7 Service | (555) 123-4567

www.foodservicetech.com | service@foodservicetech.com