

Restaurant Equipment Services LLC

SERVICE REPORT

Work Order: WO-735651 | Date: 09/02/2025

Client Information

Client	Jones-Kelly
Address	90007 Andrew Branch Suite 494, West Christopher, NE 88047
Phone	6508057300

Equipment Information

Field	Value
Machine Type	Fryers
Model	TurboCrisp 2000
Serial Number	SN73022859

Service Details

Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

Technician Information

Technician Name	Carlos Rodriguez
Technician ID	TECH-008
Certification	Master Technician Level 3
Arrival Time	02:14
Labor Hours	1.35

Technician Signature: _____ **Date:** _____

Restaurant Equipment Services LLC | 24/7 Service | (555) 123-4567

www.foodservicetech.com | service@foodservicetech.com