

Restaurant Equipment Services LLC

SERVICE REPORT

Work Order: WO-977285 | Date: 06/10/2024

Client Information

Client	Barton Ltd
Address	387 Lewis Springs, Lake Charlesstad, OR 49574
Phone	831.471.6043

Equipment Information

Field	Value
Machine Type	Fryers
Model	TurboCrisp 2000
Serial Number	SN63726890

Service Details

Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

Technician Information

Technician Name	Amanda Foster
Technician ID	TECH-019
Certification	Factory Certified Specialist
Arrival Time	23:26
Labor Hours	1.02

Technician Signature: _____ **Date:** _____

Restaurant Equipment Services LLC | 24/7 Service | (555) 123-4567

www.foodservicetech.com | service@foodservicetech.com