

# National Restaurant Repair

## SERVICE REPORT

Work Order: WO-527940 | Date: 12/07/2024

### Client Information

Client	Good Ltd
Address	PSC 0375, Box 0583, APO AP 69902
Phone	(829)512-5289x305

### Equipment Information

Field	Value
Machine Type	Fryers
Model	FryMaster XL-4000
Serial Number	SN80164464

### Service Details

#### Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

#### Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

### Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

## Technician Information

---

<b>Technician Name</b>	Sarah Williams
<b>Technician ID</b>	TECH-015
<b>Certification</b>	CFESA Certified Master
<b>Arrival Time</b>	02:11
<b>Labor Hours</b>	1.23

---

**Technician Signature:** \_\_\_\_\_ **Date:** \_\_\_\_\_

---

National Restaurant Repair | 24/7 Service | (555) 123-4567

[www.foodservicetech.com](http://www.foodservicetech.com) | [service@foodservicetech.com](mailto:service@foodservicetech.com)