

National Restaurant Repair

SERVICE REPORT

Work Order: WO-562861 | Date: 12/11/2025

Client Information

Client	Estrada PLC
Address	2058 Collier Orchard Apt. 670, Smithchester, IA 30019
Phone	001-532-442-4554x0794

Equipment Information

Field	Value
Machine Type	Fryers
Model	OilGuard Elite
Serial Number	SN89345400

Service Details

Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

Technician Information

Technician Name	Jennifer Kim
Technician ID	TECH-023
Certification	CFESA Level II Certified
Arrival Time	09:46
Labor Hours	1.77

Technician Signature: _____ **Date:** _____

National Restaurant Repair | 24/7 Service | (555) 123-4567

www.foodservicetech.com | service@foodservicetech.com