

# Metro Kitchen Equipment Service

## SERVICE REPORT

Work Order: WO-300269 | Date: 05/02/2025

### Client Information

Client	Spencer LLC
Address	5430 Miller Vista Apt. 755, Rosefort, VT 81102
Phone	929-269-0538x9361

### Equipment Information

Field	Value
Machine Type	Fryers
Model	TurboCrisp 2000
Serial Number	SN82630893

### Service Details

#### Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

#### Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

### Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

## Technician Information

---

<b>Technician Name</b>	Robert Taylor
<b>Technician ID</b>	TECH-005
<b>Certification</b>	Senior Field Technician
<b>Arrival Time</b>	08:05
<b>Labor Hours</b>	3.52

---

**Technician Signature:** \_\_\_\_\_ **Date:** \_\_\_\_\_

---

*Metro Kitchen Equipment Service | 24/7 Service | (555) 123-4567*

*www.foodservicetech.com | service@foodservicetech.com*