

Commercial Kitchen Solutions Inc

SERVICE REPORT

Work Order: WO-119607 | Date: 12/17/2024

Client Information

| | |
|---------|---|
| Client | Cooper, Cooper and Richardson |
| Address | 4403 Jeffrey Heights Apt. 093, Johnsonburgh, WA 34456 |
| Phone | 593-478-9594 |

Equipment Information

| Field | Value |
|---------------|----------------|
| Machine Type | Fryers |
| Model | OilGuard Elite |
| Serial Number | SN45970187 |

Service Details

Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

Technician Information

| | |
|------------------------|-------------------------|
| Technician Name | Mike Johnson |
| Technician ID | TECH-001 |
| Certification | EPA Universal Certified |
| Arrival Time | 21:43 |
| Labor Hours | 2.87 |

Technician Signature: _____ **Date:** _____

Commercial Kitchen Solutions Inc | 24/7 Service | (555) 123-4567

www.foodservicetech.com | service@foodservicetech.com