

Restaurant Equipment Services LLC

SERVICE REPORT

Work Order: WO-434090 | Date: 05/16/2024

Client Information

Client	Carson, Valencia and Rhodes
Address	29654 Jeffery Shoals Apt. 090, Thompsonshire, AZ 66125
Phone	3754231279

Equipment Information

Field	Value
Machine Type	Fryers
Model	CrispKing 300
Serial Number	SN24428081

Service Details

Problem Description

There's this weird smell coming from the fryer that's not the usual cooking smells - it's like something electrical is burning. The smell gets stronger when we turn the heat up high, and I'm worried something dangerous is happening inside the unit. A couple of my cooks have complained about headaches after working near it all day.

Solution Applied

Replaced overheating transformer and damaged wiring harness that was causing electrical insulation to burn and emit toxic fumes.

Parts Used

- SKU-WH-778844 - Main Wiring Harness 12-circuit with heat-resistant coating

Technician Information

Technician Name	Sarah Williams
Technician ID	TECH-015
Certification	CFESA Certified Master
Arrival Time	08:24
Labor Hours	1.42

Technician Signature: _____ **Date:** _____

Restaurant Equipment Services LLC | 24/7 Service | (555) 123-4567

www.foodservicetech.com | service@foodservicetech.com