

before motor pushes suction cup

Skin deforms by 2.7mm





Gap; no seal

