

Ummsaid Bakery Dubai Branch
 P.O. Box No: 393497, DIFC-2, Dubai - U.A.E
 Tel: +971 4 8833 303, Email: contact@riseuae.ae

Quotation Comparison - Fleet Vehicles

DATE: 05-05-2023

Sr No.	Supplier Name	Item Description	UOM Specification	Quotation reference	Requeste d Qty	UOM	Price quoted (AED)	Price Negotiated (AED)	Total purchase cost (AED)	Remarks
1	Hitec auto	O ring,leaf bush,steering hose,water pump,seal	Nos	T-31751	EST-HTC-000407	1	Nos	2,360	2,360	Lowest price, Quality,Service
2	Right solution	O ring,leaf bush,steering hose,water pump,seal	Nos	T-31751	EST1-008859	1	Nos	2,454	2,454	
3	Accenture	O ring,leaf bush,steering hose,water pump,seal	Nos	T-31751	EST1-034952	1	Nos	2,850	2,850	
4										
5										
6										
	Total									

Selected Vendor

Sr No.	Supplier Name	Item Description	UOM Specification	Quotation reference	Requeste d Qty	UOM	Price quoted	Price Negotiated	Total purchase cost	Remarks
1	Hitec auto	O ring,leaf bush,steering hose,water pump,seal	Nos	T-31751	EST1-HTC-000407	1	Nos	2,360	2,360	Lowest price, Quality,Service
2										
3										
4										

Criteria for selection

- Quality
- Service
- Lowest price

Prepared By (Fleet Coordinator)

Approved By (Deputy General manager)

Document No. USB PUR F003 Version 1
 Effective Date: 01-05-2023

Abraham Puthoor
DY. General Manager



Hitec Auto Care LLC

Warehouse No.1, Jabel Ali Industrial Area First-Dubai, UAE
Tel: +971 45911200- info@hitecauto.ae
TRN: 100506604600003

REPAIR ESTIMATE

EST-HTC-000407

04-05-2023

Mr. Ummasaid Bakery (Rise)
Attn:
Mob :
TRN :
DIP 2 - DUBAI

1550200973

Vehicle No: T-31751 DXB
Model: TOYOTA-HIACE
Year:
Chasis No: JTFPX22P1G0070365
Object No:
Milage/Km: 321209

# Item/Job Description	Qty	Rate	Amount	Disc	VAT	Net Amt
------------------------	-----	------	--------	------	-----	---------

LABOUR CHARGES

1. OIL FILTER BODY O-RING REPLACEMENT WITH SPARE PARTS (L+P) REAR RIGHT SIDE LEAF BUSH 02NOS REPLACEMENT WITH SPARE PARTS (L+P) POWER STEERINGT RETURN HOSE PIPE REMOVING AND REPLACEMENT WITH SPARE PARTS AND CONSUMABLES POWER STEERING OIL (L+P) WATER PUMB REPLACEMENT WITH SPARE PARTS (L+P) SELECTOR SEAL REMOVING AND NEW REPLACING CHARGE (L+P) TIE ROD END 2 NOS REPLACEMNT CHARGE WITH SPARE PARTS (L+P) STEERING BALL JOINT 2 NOS REPLACEMNT CHARGE WITH SPARE PARTS (L+P) ENGINE MOUNTING 02 NOS AND GEAR MOUNTING 01 NOS REMOVING AND NEW REPLACING CHARGE (LABOUR + PARTS) VALVE COVER PACKING AND PLUG SEAL REPLACEMENT WITH SPARE PARTS (L+P) SPARK PLUG 04 NOS REMOVING AND SPARK PLUG 04 NOS REPLACING CHARGE

SUB TOTAL : 997.50

28/05/2023
Abraham Putther
Dy. General M

SPARE PARTS COST

2. VALVE COVER PACKING, SPARK PLUG (4NOS), WATER PUMP, ENGINE MOUNDING, GEAR MOUNDING, FILTER BODY GASKET, SELECTOR SEAL, REAR LEAF BUSH (2NOS), STEERING RUBBER RETURN HOSE, AND LH BALL JOINT

SUB TOTAL : 1,375.50

OTHER CHARGES

3. GEAR OIL, COOLANT AND OTHER CONSUMABLES
4. LEAF SPRING BUSH PRESSING- MACHINE SHOP WORK

SUB TOTAL : 105.00

Total	2,360.00	Discount	0.00	Gross Amt:	2360.00	VAT Amt:	118.00	Net Amt.	2,478.00
-------	----------	----------	------	------------	---------	----------	--------	----------	----------

Hazique Mohamed
Asst/ Manager Sales & BD



RIGHT SOLUTION AUTO REPAIR
 Dubai Investment Park - 2
 Tel: 04 2721821, P.O Box: 72818
 Email: contact@rightsolution.ae
 www.rightsolution.ae

REPAIR ESTIMATE

ATTN. :	No. : EST1-008859
Party Name : UMMSAID BAKERY Dubai	Date : 16/01/2023
Address : DIP 2,DUBAI, UAE	
Phone : +97148833303	
Fax : +97148878751	

Reg. No.	Vehicle Make & Type	Model	K.M.	Engine No.	Chasis No.
31751 DXB-T	TOYOTA HIACE	2016	321,227		JTFPX22P1G0070365

Sl. No.	Job Description	Amount
1	OIL FILTER BODY O-RING REPLACEMENT WITH SPARE PARTS (L+P)	95.00
2	REAR RIGHT SIDE LEAF BUSH 02Nos REPLACEMENT WITH SPARE PARTS (L+P)	220.00
3	POWER STEERINGT RETURN HOSE PIPE REMOVING AND REPLACEMENT WITH SPARE PARTS AND CONSUMABLES POWER STEERING OIL (L+P)	219.00
4	WATER PUMB REPLACEMENT WITH SPARE PARTS (L+P)	360.00
5	SELECTOR SEAL REMOVING AND NEW REPLACING CHARGE (L+P)	120.00
6	TIE ROD END 2 NOS REPLACEMNT CHARGE WITH SPARE PARTS (L+P)	210.00
7	STEERING BALL JOINT 2 NOS REPLACEMNT CHARGE WITH SPARE PARTS (L+P)	190.00
8	ENGINE MOUNTING 02 NOS AND GEAR MOUNTING 01 NOS REMOVING AND NEW REPLACING CHARGE (LABOUR + PARTS)	650.00
9	VALVE COVER PACKING AND PLUG SEAL REPLACEMENT WITH SPARE PARTS (L+P)	210.00
10	SPARK PLUG 04 NOS REMOVING AND SPARK PLUG 04 NOS REPLACING CHARGE	180.00
11	NOTE:CHILLER COMPRESSOR OIL LEAK	
Less Discount :		
		Total Labour Charges
		Total Spare Parts
		Outside Work
		Others
		Gross Amount
		2,454.00
		VAT Amount (5%)
		122.70
Dhs. : TWO THOUSAND FIVE HUNDRED SEVENTY-SIX AND 70 / 100		Net Amount
		2,576.70

Remarks :

User ID : User1

This is a Computer generated Estimate and needs no signature.

TERMS & CONDITIONS:

1. A Supplementary Estimate will be submitted, If any additional damage/Parts required after dismantling.
2. Delivery subject to availability of Parts.
3. Parts price are subject to change without prior notice prices prevailing at the time of actual delivery shall be charged.

This Quotation valid for 15 days only

For RIGHT SOLUTION AUTO REPAIR



Tel.:04 - 8878253
 Fax:04 - 8878254
 P.O. Box :77387
 DIP Phase 2, Dubai - U.A.E.
 Email:accenture@eim.ae

REPAIR ESTIMATE

No. : EST1-034952

TRN: 100331803500003

ATTN. :	Date : 17/01/2023
Party Name : UMMSAID BAKERY DUBAI BRANCH	Reg No. : 31751 DXB-I
Address :	Make. : TOYOTA HIACE
Phone : 048833303	Model : 2017
Fax :	Engine No. :
TRN : 100387712100003	Chasis No. : JTFPX22P1G0070365
	Km. : 0

Sl. No.	Job Description	Amount
01	CHARGES FOR VALVE COVER GASKET , PLUG SEAL SET , WATER PUMP ASSY , ENGINE MOUNTING 2 NOS , FILTER BODY OI RING , SELECTOR OIL SEAL , BALANCE RAD BUSH 4 NOS , REAR BOTH SIDE LEAF BUSH SET , STEERING RETURN HOSE ,CUT BUSH 2 NOS , TIE ROD END 2 NOS , RACK END 2 NOS NEW REPLACING [MATERIAL + LABOUR]	2,850.00
<i>Remarks :</i>		
Dhs. : TWO THOUSAND NINE HUNDRED NINETY-TWO AND 50 / 100		
		Total Labour Charges
		Total Spare Parts
		Outside Work
		Others 2,850.00
		Total Amount 2,850.00
		Discount
		VAT (5%) 142.50
		Net Amount 2,992.50

User ID : NITHIN

This is a Computer generated Estimate and needs no signature.

For ACCENTURE AUTOMOTIVES GARAGE

TERMS & CONDITIONS:

1. A Supplementary Estimate will be submitted, If any additional damage/Parts required after dismantling.
2. Delivery subject to availability of Parts.
3. Parts price are subject to change without prior notice prices prevailing at the time of actual delivery shall be charged.

This Quotation valid for 15 days only