

Umm Said Bakery Dubai Branch
 P.O Box No: 385487, DIFC - Dubai - U.A.E.
 Tel: +971 4 8833 203, Email: contracts@ummsaid-uae.com
 Quotations, Consultation, - Fleet Vehicles

Date: 15-03-2023

Sl.No.	Supplier Name	Item Description	UOM	Specification	Quotation Reference	Requested Qty.	UOM	Price quoted (AED)	Total purchase. cost (AED)	Remarks
1	All Furnit	chiller work	Nos	T-31795	E8178HJ-230118282	1	Nos	2,280.00	2,280.00	Lowest price, Quality Service
2	Right solution	chiller work	Nos	T-31795	EST1-L0081812	1	Nos	2,600.00	2,600	
3	Accenture	chiller work	Nos	T-31795	EST1-034844	1	Nos	2,600.00	2,600	
4										
5										
6										
7										
8										
9										
10										
		Total								

Sl.No.	Supplier Name	Item Description	UOM	Specification	Quotation reference	Requested Qty.	UOM	Price quoted (AED)	Total purchase. cost (AED)	Remarks
1	All Furnit	chiller work	Nos	T-31795	E8178HJ-230118282	1	Nos	2,280.00	2,280	Lowest price, Quality Service
2										
3										
4										
5										
6										

Criteria for selection:

- A Quality
- A Service
- A Lowest price
- A

Prepared By (Procurement)

Approved By (Deputy General Manager)

Effective Date: 11-03-2023

APPROVED

SIGN: 

DATE: 11-03-2023



1550200046

ESTIMATE

M/s. Umm Said Bakery Dubai Branch

P.O.Box : 393497 Dubai - UAE

Tel : 04 8833303 Fax : 04 8378751

Alt: Mr. Ajmal Aboobacker / 056 4020247

E-Mail: ajmal@rise-uae.ae

T.R.No : 100387712100003

T.R.No	:	100475060800003
EST.No	:	EST/SHJ-23/16282
EST.Date	:	02/01/2023
Vehicle	:	31755 DXB
Unit	:	KYSOR

Description	Qty	Price (AED)	Amount (AED)
Having inspected the refrigeration unit mounted on your above vehicle, we note that the below mentioned parts need to be repaired / replaced:	1	2,280.00	2,280.00
Refrigeration unit repair :- Cost and Charges for checking and replacing Compressor TM 15 12V, receiver drier, hose with fitting (5/8, 1/2, 3/8) and 134 gas charging of the refrigeration unit mounted on your above vehicle.		Total	2,280.00
AED TWO THOUSAND THREE HUNDRED NINETY FOUR ONLY		VAT 5%	114.00
		Net Amount	2,394.00

We trust you will find the above to be in line with your requirements and look forward to hearing from you at your earliest convenience.
Assuring you of our best services at all times and in the meantime,

Thanking You,
For Al Furat Refrigeration Devices Co LLC

Hazique Mohamed
Asst/ Manager Sales & BD

Sonu George
Asst. Manager - Maintenance
+971 552193076

- Additional works or materials that may be required in the event of our diagnosing any further faults with the system will be charged extra to your account.
- Please sign and return this form as a token of your acceptance of the above.
- Payment Terms : 50% advance, balance on completion.
- Validity : 15 days from date hereof.

Approved by

ooo oo oo oo oo

Al Furat Refrigeration Devices Co LLC
P.O.Box: 393497, Sector 10, Al Quoz, Dubai, UAE
Phone: +971 4 8378751, Fax: +971 4 8378752
Email: ajmal@rise-uae.ae
Web: www.alfurat.ae

RIGHT SOLUTION AUTO REPAIR
Dubai Investment Park - 2
Tel: 04 2721821, P.O Box: 72818
Email: contact@rightsolution.ae
www.rightsolution.ae

RIGHT SOLUTION

REPAIR ESTIMATE

ATTN. :	No. : EST1-008812
Party Name :	UMMSAID BAKERY Dubai
Address :	DIFC 2,DUBAI, UAE
Phone :	+97148833303
Fax :	+97148878753
	Date : 04/01/2023

Reg. No.	Vehicle Make & Type	Model	K.M.	Engine No.	Chassis No.
31755 DXB-T	TOYOTA HIACE	2016	0		JTFP922P6G9070359
Sl. No.	Job Description				Amount
1	COMPRESSOR REMOVING AND COMPRESSOR AND DRIER FILTER AND HOSE AND AC GAS FILLING AND LINE CLEANING CHARGE				2,600.00
	Less Discount :			Total Labour Charges	
				Total Spare Parts	
				Overhead Work	
				Others	
				Gross Amount	2,600.00
				VAT Amount (5%)	130.00
				Net Amount	2,730.00

Remarks:

User ID : User1

This is a Computer generated Estimate and needs no signature.

TERMS & CONDITIONS:

1. A Supplementary Estimate will be submitted, if any additional damage/Parts required after dismantling.
 2. Delivery subject to availability of Parts.
 3. Parts price are subject to change without prior notice prices prevailing at the time of quoted delivery shall be charged.

This Quotation valid for 15 days only

For RIGHT SOLUTION AUTO REPAIR



Tel. 04 - 8878253
 Fax. 04 - 8878254
 P.O. Box 77307
 DIFC Phase 2, Dubai - UAE
 Email: accenture@dm.com.ae

REPAIR ESTIMATE

No. : EST1-034844

TRN: 100331803500003

ATTN. :
 Party Name : UMMSAID BAKERY DUBAI BRANCH
 Address :
 Phone : 048833303
 Fax :
 TRN : 100387712100003

Date : 04/01/2023
 Reg No. : 31755 DXB-T
 Make : TOYOTA HIACE
 Model : 2016
 Engine No. :
 Chassis No. : TFPX22P6G0070359
 Km. : 0

Sl. No.	Job Description	Amount
01	CHARGES FOR REAR A/C COMPRESSOR , DRIER , RECEIVER HOSE CHANGE	2,600.00

Remarks :

Dhs. : TWO THOUSAND SEVEN HUNDRED THIRTY ONLY

Total Labour Charges	
Total Spare Parts	
Overtime Work	
Others	2,600.00
Total Amount	2,600.00
Discount	
VAT (5%)	130.00
Net Amount	2,730.00

User ID : RITHIN

This is a Computer generated Estimate and needs no signature.

TERMS & CONDITIONS:

1. A Supplementary Estimate will be submitted, if any additional damage/Parts required after demarcation.
 2. Delivery subject to availability of Parts.
 3. Parts price are subject to change without prior notice prices prevailing at the time of actual delivery shall be charged.
- The Quotation valid for 15 days only

For ACCENTURE AUTOMOTIVES GARAGE

Umm Said Bakery Dubai Branch									
P.O Box No: 33477, DIFC, Dubai - U.A.E Tel: +971 4 383 355, Email: commerc@chesan.ae									
Quotation Competition - Fleet Vehicles									
Date: 27-02-2013									
Sl.No.	Supplier Name	Item Description	UCM	Specification	Quotation reference	Requested Qty	UCM	Price quoted (AED)	Total purchase cost (AED)
1	Al Furat	chiller belt and pully	Nos	Vehicle Maint.	ESTTSH-J-22117014	1	Nos	225.00	225
2									
3									
4									
5									
6									
7									
8									
9									
10									
Total									
Selected Vendor									
Sl.No.	Supplier Name	Item Description	UCM	Specification	Quotation reference	Booked Qty	UCM	Price quoted (AED)	Total purchase cost (AED)
1	Al Furat	chiller belt and pully	Nos	Vehicle Maint.	ESTTSH-J-22117014	1	Nos	225.00	225
2									
3									
4									
5									
6									

Criteria for selection

- ▲ Quality
- ▲ Service
- ▲ Lowest price
- ▲

Approved by (Director General manager)
[Signature]

Document No. USE PUR 003 Version 01 Date 01-03-2013

1550200433



ESTIMATE

M/s. Ummsald Bakery Dubai Branch

P.O.Box : 393497 Daubi - UAE

Tel : 04 8833303 Fax : 04 8878751

Attn: Mr. Ajmal Aboobacker / 056 4020247

E-Mail:ajmal@rise-uae.ae

T.R.No : 100387712100003

T.R.No : 100475060800003

EST.No : EST/SHJ-23/17014

EST.Date : 27/02/2023

Vehicle : 74623 DXB

Unit : HT-100

Description	Qty	Price (AED)	Amount (AED)
Having inspected the refrigeration unit mounted on your above vehicle, we note that the below mentioned parts need to be repaired / replaced:			
Refrigeration unit repair :- Cost and Charges for checking and replacing belt & idler pulley of the refrigeration unit mounted on your above vehicle.	1	225.00	225.00
AED TWO HUNDRED THIRTY SIX AND FILS TWENTY FIVE ONLY		Total	225.00
		VAT 5%	11.25
		Net Amount	236.25

We trust you will find the above to be in line with your requirements and look forward to hearing from you at your earliest convenience.
Assuring you of our best services at all times and in the meantime,

Thanking You,

For Al Furat Refrigeration Devices Co LLC

Sonu George

Asst. Manager - Maintenance

+971 552193076

Abraham Puthen
Dy. General Manager

Hazique Mohamed
Asst/ Manager Sales & B.

- Additional works or materials that may be required in the event of our diagnosing any further faults with the system will be charged extra to your account.
- Please sign and return this form as a token of your acceptance of the above.
- Payment Terms : 50% advance , balance on completion.
- Validity : 15 days from date hereof.

Approved by



الفرات
Al Furat Group Co. LLC
P.O BOX: 3980, Sharjah - UAE
Tel: +971 6 5342622 Mobi: +971 56 4419682
Email: furat@furm.ae
Web: www.alfuratgroup.ae