

Industrial Equipment Inspection Report

Report ID	INS-2026-014
Equipment	Pump P-101
Inspector	Rahul Sharma

Routine inspection found vibration of 8.2 mm/s, bearing temperature 78 C, and oil leakage near BR-220. Alignment and bearing inspection recommended.