

Hyundai i20 — Automotive Diagnostic Test Manual

Synthetic test document for AutoDiag AI Knowledge Base ingestion and RAG retrieval.

1. Vehicle Information

Vehicle: Hyundai i20

Example model year: 2019

Engine: Petrol

2. Engine Shaking at Idle

An engine that shakes or runs roughly while stopped at idle may have several possible causes. Common diagnostic areas include ignition, fuel delivery, intake air, sensors, and engine mechanical condition.

3. Diagnostic Trouble Code P0301

P0301 — Cylinder 1 Misfire Detected. Possible areas to inspect include the cylinder 1 spark plug, ignition coil, injector, intake or vacuum leaks, wiring/connectors, and engine compression.

4. Suggested Diagnostic Sequence

1. Confirm the complaint and record all stored and pending DTCs.
2. Inspect the spark plug and ignition coil for cylinder 1.
3. Check coil and injector electrical connectors.
4. Inspect for intake or vacuum leaks.
5. Check fuel delivery if ignition components are satisfactory.
6. Perform a compression or mechanical test when appropriate.
7. Follow the applicable manufacturer verification procedure before replacing parts.

5. Important Note

This synthetic document is only for testing AutoDiag AI ingestion. It is not an official Hyundai service manual and must not be treated as an authoritative repair procedure.