

Density by category, k = 10

k = 10, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Aspect ratio (lower = more compact), k = 10

k = 10, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Center of mass offset (lower = better balanced), k = 10

k = 10, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Cost per packing, k = 10

k = 10, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Contacts per part (higher = more parts touch through the clearance), k = 10

k = 10, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Isolated parts (parts with no contact, i.e. nothing to support them), k = 10

k = 10, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Density by category, k = 20

k = 20, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Aspect ratio (lower = more compact), k = 20

k = 20, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Center of mass offset (lower = better balanced), k = 20

k = 20, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Cost per packing, k = 20

k = 20, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Contacts per part (higher = more parts touch through the clearance), k = 20

k = 20, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Isolated parts (parts with no contact, i.e. nothing to support them), k = 20

k = 20, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Density by category, k = 30

k = 30, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Aspect ratio (lower = more compact), k = 30

k = 30, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Center of mass offset (lower = better balanced), k = 30

k = 30, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Cost per packing, k = 30

k = 30, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV




Contacts per part (higher = more parts touch through the clearance), k = 30

k = 30, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV



Isolated parts (parts with no contact, i.e. nothing to support them), k = 30

k = 30, open mode, 60-part categories (23 real shapes); error bars = 99% confidence interval of the mean; n per bar in the leaderboard CSV



Density versus part count k

shaded band = 99% confidence interval of the mean

