

Read by terminal name, not by physical pin position.

Solid dot = joined wires. Gapped crossing = no connection. W-numbers match the connection register.

BENCH DESIGN — H1-H5 QUALIFICATION STILL REQUIRED

X1 labels are project signals, NOT the machine's numbered connector cavities.

