

SAFETY DIRECTIVE: LOTO

Lockout / Tagout (LOTO) Procedures

Before performing any physical maintenance, bearing inspection, or internal testing on an electric motor, the following LOTO steps **MUST** be verified:

1. **Identify the Energy Source:** Locate the main disconnect switch for the specific motor ID (e.g., M003).
2. **Isolate:** Turn the switch to the OFF position.
3. **Lock and Tag:** Apply your personal padlock to the disconnect switch. Attach a highly visible tag with your name, date, and reason for lockout.
4. **Verify (Try It):** Attempt to start the motor from the local control panel and the remote SCADA/dashboard to ensure it does not energize.
5. **Test for Voltage:** Open the motor junction box and use a calibrated multimeter to verify zero voltage across all phases and to ground.

