Leader Training Topic:

These procedures cover the processes and tasks required to correctly lock up the facility each day.

August 6, 2024

CNC

- Remove all tools from the machine spindles.
- Turn machines to the OFF home position.
- Turn all machines OFF.
- Turn the air compressors OFF.
- Organize the department area.
- Ensure there are no overflowing trash cans.
- Turn all fans OFF.
- Close and lock container doors.
- Close and lock all doors
 - o 3 pedestrian exit doors
 - Roll down door
- Turn lights OFF.

Gunsmith

- Turn Mill 1 & 2 OFF.
- Place all tools and drills in the correct toolbox.
- Turn all fans OFF.
- Shut down the air compressor.
- Close and latch the roll down door.
- Close and lock the pedestrian exit door.
- In the grinding room:
 - Turn all grinders OFF.
 - Turn fans OFF.
 - Turn lights OFF.
 - Turn OFF exhaust fans.
 - Close both doors.

Turn off pressure washer

Turn off water spigot

Plugging & Layup

- Turn OFF fans.
 - Break out area
 - Layup room
 - Assembly area
- Close container doors
- Turn OFF lights.
 - Mixing shed
 - Break out area
 - Break room
 - Hot room
 - Layup room
- Close the door to the mixing shed.
- Ensure the oven timers are set to turn off OFF.
- Close and latch both roll down doors in the oven area.
- Close the pedestrian exit door.

Paint

- Clean and break down paint guns.
- Turn OFF paint booth fan and lights.
- Turn OFF air compressor.
- Turn OFF all fans.
- Turn OFF all Z-rack lights.
- Close all cabinets and the paint closet.

General Tasks

- Turn OFF bathroom lights.
- Make sure the coffee pot is OFF.
- Verify all air compressors are OFF.
- Close and lock all container doors.
- Close and latch the roll down doors.
- Turn OFF overhead fans.
- Ensure all lights are OFF.
- Lock all external doors.
- Ensure the security gate closes.
- Check the front office if you are the last person to leave, set the alarm and lock the front door.
- Walk through the sanding shed turn off lights and remove tools

Front Office

- Turn OFF the dehumidifier.
- Ensure bathroom and office lights are OFF.
- Ensure hall and porch lights are ON.
- Check the back building if you are the last person to leave, set the alarm and lock the front door.
- Ensure the security gate is closed.

Questions - Changes?

final walk through turn off lights in cnc area

Glenn create a final walk through calendar for leaders