

		Caution	
		Unit ID: 321.LQ120 (T)	Asset ID: 30626957
		Description: Roller Lubrication Unit (Tank)	
Account Information		Sample Information	Equipment Information
ID: 208948 Name: Reliance Heavy Industries Address: Kattameya-Sokhna Road, Suez, 00000 EG		Sample ID: 26124405240 Service Level: Enhanced Bottle ID: b105176070 Tested Lubricant: MOBIL SHC 639	Asset Class: Circulating System Manufacturer: FLS Model: N/A Lubricant: MOBIL SHC 639
Recommendation/Comments			
ACTION REQUIRED - EXCESSIVE WATER CONTAMINATION. Determine source of water and take corrective action. Analyze the oil with an on-site water test if accessible. Potential sources of water include: a. Leaking seals; b. Condensation resulting from low operating temperatures or prolonged shutdowns; c. Compromised oil cooler; d. Direct exposure to atmosphere as a result of compromises to system components (i.e. improperly sealed tank fill access point. Remove water from oil using centrifuges or dehydration units, or drain the oil and recharge the system with new oil. Resample the system after corrective measures have been implemented. Contact your ExxonMobil representative for further assistance if necessary.			
Sample Timeline			
<u>26 Apr 2026 9:17 AM - Hassan Mostafa - In Service Oil Sample</u>: Comments: Photo:			