

Mobil™

Unit ID: R2.432.MD140 (N32)

Asset ID: 40109808

Description: Kiln #2 Main drive gearbox (N32)

Account Information

Sample Information

Equipment Information

ID: 208948

Name: Reliance Heavy Industries

Address: Kattameya-Sokhna Road, Suez, 00000 EG

Sample ID: 26124405239

Service Level: Enhanced

Bottle ID: b105154304

Tested Lubricant: MOBILGEAR 600 XP 460

Asset Class: Gear Drive

Manufacturer: FLENDER (SIEMENS)

Model: H3SH20

Lubricant: MOBILGEAR 600 XP 460

Sample Data & Trends

Report Status

Alert

Alert

Caution

Caution

Caution

Sample ID

2525916922326004401264260616302102609031322926124405239

Service Level

Enhanced

Enhanced

Enhanced

Enhanced

Enhanced

Bottle ID

b098287429

b105107808

b093868835

b093867217

b105154304

Tested Lubricant

MOBILGEAR 600 XP 460

MOBILGEAR 600 XP 460

MOBILGEAR 600 XP 460

MOBILGEAR 600 XP 460

MOBILGEAR 600 XP 460

Sampled

10 Sep 2025

16 Dec 2025

01 Feb 2026

12 Mar 2026

26 Apr 2026

Reported

18 Sep 2025

05 Jan 2026

03 Mar 2026

01 Apr 2026

05 May 2026

Equipment Age

Oil Age

Make-up Volume

Oil Changed

Filter Changed

Contamination Rating

Alert

Alert

Caution

Caution

Caution

Equipment Rating

Alert

Normal

Normal

Normal

Normal

Lubricant Rating

Normal

Normal

Normal

Normal

Normal

ISO Code (4/6/14)

Particle Count >4um

Particle Count >6um

Particle Count>14um

PQ Index

25

52

20

22

30

Visc@40C (cSt)

428.4

410.1

451.7

433.3

447.4

Oxidation (Ab/cm)

2

1

0

0

1

Water (Vol%)

0.220

0.300

0.040

0.040

0.050

Ag (Silver)

0

0

0

0

0

Al (Aluminum)

38

5

1

0

1

Cr (Chromium)

1

0

0

0

0

Cu (Copper)

7

0

0

0

0

Fe (Iron)

41

43

15

22

25

Mo (Molybdenum)

2

2

0

0

0

Ni (Nickel)

0

0

0

0

0

Pb (Lead)

0

0

0

0

0

Sn (Tin)

0

0

0

0

0

K (Potassium)

0

0

0

0

0

Na (Sodium)

0

0

0

0

0

Si (Silicon)

21

17

17

10

7

B (Boron)

12

32

20

10

0

Ba (Barium)

0

0

0

0

0

Ca (Calcium)

224

188

45

45

24

Mg (Magnesium)

2

5

2

0

2

P (Phosphorus)

317

399

410

400

400

Zn (Zinc)

48

22

0

3

4

Viscosity

475

450

425

400

10 Sep 2025

16 Dec 2025

01 Feb 2026

12 Mar 2026

26 Apr 2026

Visc@40C (cSt)

Wear

50

25

0

10 Sep 2025

16 Dec 2025

01 Feb 2026

12 Mar 2026

26 Apr 2026

Ag (Silver)

Al (Aluminum)

Cr (Chromium)

Cu (Copper)

Fe (Iron)

Ni (Nickel)

Pb (Lead)

Sn (Tin)

Contaminants

30

20

10

0

10 Sep 2025

16 Dec 2025

01 Feb 2026

12 Mar 2026

26 Apr 2026

Na (Sodium)

K (Potassium)

Si (Silicon)

Physical Properties

3

2

1

0

10 Sep 2025

16 Dec 2025

01 Feb 2026

12 Mar 2026

26 Apr 2026

Water (Vol%)

Oxidation (Ab/cm)

	Caution	
	Unit ID: R2.432.MD140 (N32)	Asset ID: 40109808
	Description: Kiln #2 Main drive gearbox (N32)	
Account Information	Sample Information	Equipment Information
ID: 208948 Name: Reliance Heavy Industries Address: Kattameya-Sokhna Road, Suez, 00000 EG	Sample ID: 26124405239 Service Level: Enhanced Bottle ID: b105154304 Tested Lubricant: MOBILGEAR 600 XP 460	Asset Class: Gear Drive Manufacturer: FLENDER (SIEMENS) Model: H3SH20 Lubricant: MOBILGEAR 600 XP 460
Recommendation/Comments		
ACTION REQUIRED - EXCESSIVE WATER CONTAMINATION. Determine source of water and take corrective action. Analyze the oil with an on-site water test if accessible. Potential sources of water include: a. Leaking seals; b. Condensation resulting from low operating temperatures or prolonged shutdowns; c. Compromised oil cooler; d. Direct exposure to atmosphere as a result of compromises to system components (i.e. improperly sealed tank fill access point. Remove water from oil using centrifuges or dehydration units, or drain the oil and recharge the system with new oil. Resample the system after corrective measures have been implemented. Contact your ExxonMobil representative for further assistance if necessary. ADMINISTRATION - PARTICLE COUNT DATA NOT REPORTED. The sample is heavily contaminated with visible sediment. Oil samples that contain significant levels of any contaminant can damage the laboratory's precision equipment. As a result, the particle count test was not completed, and analysis could not be provided. Before sending future samples to the laboratory, please ensure that no signs of visible sediment contamination are present. Consider the following: 1. The sample may not be representative of the system if it was acquired from a non-turbulent area (i.e. tank bottom); 2. Installing sample ports helps ensure that the sample is taken from the same location every time; 3. Tank fill caps and breathers might not be properly secured; 4. The filter / centrifuge may be operating incorrectly. If the sample was representative of the system, change the oil immediately to prevent equipment damage. Contact your ExxonMobil representative for further assistance if necessary.		
Sample Timeline		
26 Apr 2026 11:35 AM - Hassan Mostafa - In Service Oil Sample : Comments: Photo:		