Preliminary Report of Accident

U.S. Department of Labor
Mine Safety and Health Administration

PR001 11/13/2025

1. Accident Type	2. Accident Classification	3. Date/Time of Accident	4. Date/Time of Death	5. Fatal Case No
F - Fatal Injury	12 - Powered Haulage	11/06/2025 1:30 AM	11/06/2025 04:16 AM	FAI-F026D09-1

6. Mine Information
- **a) Mining Company Name:** Mettiki Coal WV, LLC
- **b) Mine Name:** Mountain View Mine
- **c) Parent of Mining Company:** Alliance Resource Partners LP

7. Mine Location Information			8. Mine ID Number	9. Union
a) City	b) County	c) State		
OAKLAND	Tucker	WV	46-09028	

10. Primary Mineral Mined	11. Number of Employees				
	a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other
Bituminous Coal Underground Mining	242	200		42	

12. Contractor Name	13. Contractor Union	14. Contractor ID Number

15. Contractor Address			
a) City	b) County	c) State	d) Zip Code

16. Number of Contractor Employees				
a) Total	b) Underground	c) Open Pit/Quarry	d) Mill/Prep Plant	e) Other

17. Number of Persons in Mine at Time of Accident		18. Number of Persons Unaccounted for	
a) Mine Employees	b) Contractor Employees	a) Mine Employees	b) Contractor Employees
45		0	

19. Accident Location	20. Mining Height
01 - Underground	9 Feet 0 Inches

21. Nonfatal Injuries	22. Fatal Injuries
1	1

23. Victims Information

Joseph D Mitchell

a) First Name	a) MI	a) Last Name	b) Age	c) Regular Job Title	d) Activity at Time of Accident	Employee
Joseph	D	Mitchell	25	Scoop-Utility	Retrieving Supplies	Mine Employee

24. Mining Experience

a) Total Experience	b) Experience at the Mine	c) Experience at the Activity at the Time of the Accident	d) Experience with Contractor
3 Years 3 Weeks Days	3 Years 2 Weeks Days	3 Years 2 Weeks Days	Years Weeks

25. Autopsy Performed	If Yes, Location

26. Mine Telephone No.

27. Description of Accident (include equipment involved, the exact location in the mine, and status and recovery operations)

Two locomotives and six supply cars lost control and struck a scoop, derailing one of the locomotives and a supply car. The miner died after being pinned beneath a supply car.

The information provided in this notice is based on preliminary data ONLY and does not represent final determination regarding the nature of the incident or conclusions regarding thecause of the accident.

28. Equipment Manufacturer	29. Model	
Not listed Brookville / Eimco	30 Ton Motor / 913 Scoop	
30. District	**32. Field Office**	**33. Event Number**
C0300 - Morgantown District	C0301 - Morgantown WV Field Office	F026D09

34. Accident Investigator

First Name	MI	Last Name
David	P	Wamsley

35. MSHA Person Notified

First Name	MI	Last Name	Date/Time Notified
Ken		Cosgrave	11/06/2025 2:01 AM

36. Type of Report	37. Name of Preparer	
	Full Name	Date Prepared
Initial	David P Wamsley	11/06/2025

38. Reason for Amendment