

Tools and requirements



hardware

- laptop
- Wires
- Multimeter
- Arduino
- ▶ Usb ttl
- Screwdrivers
- lc test clip
- raspberry pi 2 or above
- Digispark
- Raspberry pi zero w
- Proxmark3 optional
- Rtlsdr
- Ir transceivers
- Msr reader optional
- Soldering tools optional
- Lantap pro diy or buy



software

- *unix machine
- Linux commands:
 - dd
 - file
 - Unsqashfs
 - Uncramfs
 - Strings
 - Grep
 - tar
- > Tools:
 - Binwalk
 - Fmk



software

- rpitx
- Arduino ide
- Minicom
- wifipwn
- Poisonpi
- P4wnp1
- Wireshark
- Ghidra advanced
- Radare advanced
- Ida pro advanced
- Ltrace , strace , objdump

