

ITEM	PHOTO	
OV-001 .	No Image	
Location: Level 5, Corridor A - East Wing	Inspector's comments: 1. General visual inspection completed. No visible cracks or structural concerns. Inspector: Test Inspector (TEST-001)	
OV-002 .	No Image	
Location: Level 5, Corridor B - West Wing	Inspector's comments: 1. Ceiling finish in good condition. Minor staining near HVAC vent. 2. Recommend annual inspection. Inspector: Test Inspector (TEST-001)	

ITEM	PHOTO	ASSESSMENT TYPES
DA-001	No Image	Crack: ☐ FC1 ☒ WC1 ☒ FC2 ☐ WC2 ☒ FC3 ☐ WC3 ☐ FC4 ☐ WC4
		Bent: ☒ B1 ☐ B3 ☐ B2 ☐ B4
		Damage: ☐ D1 ☐ D3 ☐ D2 ☐ D4
Location:	Inspector's comments: 1. Hairline crack approx 0.3mm width, 450mm length. 2. Located on beam soffit. Monitor quarterly. Inspector: Test Inspector (TEST-001)	Impact Category: Minor: ☐ Moderate: ☒ Major: ☐
DA-002	No Image	Crack: ☐ FC1 ☐ WC1 ☐ FC2 ☐ WC2 ☐ FC3 ☐ WC3 ☒ FC4 ☐ WC4
		Bent: ☐ B1 ☒ B3 ☐ B2 ☐ B4
		Damage: ☐ D1 ☒ D3 ☐ D2 ☒ D4
Location:	Inspector's comments: 1. Spalling concrete with exposed reinforcement. Approx 200x300mm area. 2. Urgent repair required. Area cordoned off. Inspector: Test Inspector (TEST-001)	Impact Category: Minor: ☐ Moderate: ☐ Major: ☒