

Location: Level 5, Corridor A - East Wing
Section: Block A

- ☒ Internal
☐ External
- ☐ M&E
☐ Public facilities

ITEM	PHOTO	
OV-001.	No Image	
Location: Level 5, Corridor A - East Wing		Inspector's comments: 1. General visual inspection completed. No visible cracks or structural concerns. Inspector: Test Inspector (TEST-001)
OV-002.	No Image	
Location: Level 5, Corridor B - West Wing		Inspector's comments: 1. Ceiling finish in good condition. Minor staining near HVAC vent. 2. Recommend annual inspection. Inspector: Test Inspector (TEST-001)

Location: Beam B3/4 - Junction with Column C3

Section: Block B

☐ Internal
☒ External

☐ M&E
☐ Public facilities

ITEM	PHOTO	ASSESSMENT TYPES
DA-001.	No Image	Crack: ☐ FC1 ☒ FC2 ☒ FC3 ☐ FC4 ☒ WC1 ☐ WC2 ☐ WC3 ☐ WC4 Bent: ☒ B1 ☐ B2 ☐ B3 ☐ B4 Damage: ☐ D1 ☐ D2 ☐ D3 ☐ D4
Location: Beam B3/4 - Junction with	Inspector's comments: 1. Hairline crack approx 0.3mm width, 450mm length. 2. Located on beam soffit. Monitor quarterly. Inspector: Test Inspector (TEST-001)	Impact Category: Minor: ☐ Moderate: ☒ Major: ☐
DA-002.	No Image	Crack: ☐ FC1 ☐ FC2 ☐ FC3 ☒ FC4 ☐ WC1 ☐ WC2 ☐ WC3 ☐ WC4 Bent: ☐ B1 ☐ B2 ☒ B3 ☐ B4 Damage: ☐ D1 ☐ D2 ☒ D3 ☒ D4
Location: External wall Panel 7, Ground Floor -	Inspector's comments: 1. Spalling concrete with exposed reinforcement. Approx 200x300mm area. 2. Urgent repair required. Area cordoned off. Inspector: Test Inspector (TEST-001)	Impact Category: Minor: ☐ Moderate: ☐ Major: ☒