

Location: Level 5, Corridor A - East Wing
Section: Block A

☒ Internal	☐ M&E
☐ External	☐ Public facilities

ITEM	PHOTO	
OV-001 .	No Image	
Location: Level 5, Corridor A - East Wing		Inspector's comments: 1. General visual inspection completed. No visible cracks or structural concerns. Inspector: Test Inspector (TEST-001)
OV-002 .	No Image	
Location: Level 5, Corridor B - West Wing		Inspector's comments: 1. Ceiling finish in good condition. Minor staining near HVAC vent. 2. Recommend annual inspection. Inspector: Test Inspector (TEST-001)

Location: Beam B3/4 - Junction with Column C3

Section: Block B

☐ Internal	☐ M&E
☒ External	☐ Public facilities

ITEM	PHOTO	ASSESSMENT TYPES								
DA-001 .	No Image	Crack: <table><tr><td>☐ FC1</td><td>☒ WC1</td></tr><tr><td>☒ FC2</td><td>☐ WC2</td></tr><tr><td>☒ FC3</td><td>☐ WC3</td></tr><tr><td>☐ FC4</td><td>☐ WC4</td></tr></table>	☐ FC1	☒ WC1	☒ FC2	☐ WC2	☒ FC3	☐ WC3	☐ FC4	☐ WC4
☐ FC1		☒ WC1								
☒ FC2		☐ WC2								
☒ FC3		☐ WC3								
☐ FC4	☐ WC4									
	Bent: <table><tr><td>☒ B1</td><td>☐ B3</td></tr><tr><td>☐ B2</td><td>☐ B4</td></tr></table>	☒ B1	☐ B3	☐ B2	☐ B4					
☒ B1	☐ B3									
☐ B2	☐ B4									
	Damage: <table><tr><td>☐ D1</td><td>☐ D3</td></tr><tr><td>☐ D2</td><td>☐ D4</td></tr></table>	☐ D1	☐ D3	☐ D2	☐ D4					
☐ D1	☐ D3									
☐ D2	☐ D4									
Location:	Inspector's comments: 1. Hairline crack approx 0.3mm width, 450mm length. 2. Located on beam soffit. Monitor quarterly. Inspector: Test Inspector (TEST-001)	Impact Category: <table><tr><td>Minor:</td><td>☐</td></tr><tr><td>Moderate:</td><td>☒</td></tr><tr><td>Major:</td><td>☐</td></tr></table>	Minor:	☐	Moderate:	☒	Major:	☐		
Minor:	☐									
Moderate:	☒									
Major:	☐									
DA-002 .	No Image	Crack: <table><tr><td>☐ FC1</td><td>☐ WC1</td></tr><tr><td>☐ FC2</td><td>☐ WC2</td></tr><tr><td>☐ FC3</td><td>☐ WC3</td></tr><tr><td>☒ FC4</td><td>☐ WC4</td></tr></table>	☐ FC1	☐ WC1	☐ FC2	☐ WC2	☐ FC3	☐ WC3	☒ FC4	☐ WC4
☐ FC1		☐ WC1								
☐ FC2		☐ WC2								
☐ FC3		☐ WC3								
☒ FC4	☐ WC4									
	Bent: <table><tr><td>☐ B1</td><td>☒ B3</td></tr><tr><td>☐ B2</td><td>☐ B4</td></tr></table>	☐ B1	☒ B3	☐ B2	☐ B4					
☐ B1	☒ B3									
☐ B2	☐ B4									
	Damage: <table><tr><td>☐ D1</td><td>☒ D3</td></tr><tr><td>☐ D2</td><td>☒ D4</td></tr></table>	☐ D1	☒ D3	☐ D2	☒ D4					
☐ D1	☒ D3									
☐ D2	☒ D4									
Location:	Inspector's comments: 1. Spalling concrete with exposed reinforcement. Approx 200x300mm area. 2. Urgent repair required. Area cordoned off. Inspector: Test Inspector (TEST-001)	Impact Category: <table><tr><td>Minor:</td><td>☐</td></tr><tr><td>Moderate:</td><td>☐</td></tr><tr><td>Major:</td><td>☒</td></tr></table>	Minor:	☐	Moderate:	☐	Major:	☒		
Minor:	☐									
Moderate:	☐									
Major:	☒									