

No.: 06SO-2 January 31, 2006

TO: Distributors and On-Highway Dealers – U.S. and Canada

ATTN.: General Manager, Sales Manager, Parts Manager and Service Manager

FROM: R. P. Dziadzio, Manager, Service Operations

SUBJECT: Change in Policy for Injector Pre-Authorizations

DDC issued the requirement for injector pre-authorization in 2001 (01SO-5) to service outlets for warrantable injector repairs. DDC will now allow replacement of 1 or 2 injectors to be performed without pre-authorization effective January 31, 2006. In addition there is a small group of engines that DDC will allow all injectors to be replaced on the engine without pre-authorization for two specific conditions. The attached flow diagram can be used to determine if an authorization is required.

The adjusted procedure remains in effect for all Series 50 and 60 on-highway engines.

It will insure that all available troubleshooting expertise is exhausted prior to injector replacement. You do not need an authorization number if the engine/injector is beyond the warranty or P-3 coverage but similar diagnostics should be utilized when treating an out of warranty condition.

To summarize:

After determination of injector failure under warranty or P-3 and 3 or more injectors require replacement:

- 1) Call 313-592-5800 for an Injector Authorization Number
- 2) Write the authorization number plainly on the injector box as well as the other requested information for return to DDC
- 3) Return the injectors following normal return procedures
- 4) Write the authorization number in the claim authorization field and in the narrative

Please share this revised process with all personnel who are impacted by this change. Please call 313-592-5800 or submit a Warranty Inquiry ticket if you have any questions regarding this change in the program.

On Highway Injector Authorization

