



Terrasat Communications Inc.
315 Digital Drive, Morgan Hill, CA 95037

Document Number:	FRN-23820-0BIN
Description:	Release Notes for RXR/RXI
Revision:	0109
Date:	November 13, 2025
Prepared By:	Ajay Sharma

1 Release Notes

RX1+1 with TERX serial number

Revision

1.00

- First shipping version.

1.01

- Added manual control of internal 10 MHz when both are equipped.
- Added internal 10 MHz #1 failure alarm when both are equipped.
- Converted HHT menu system to a scrolling system not based on selecting number keys.

1.02

- Fixed problem with sensors web page not fully loading.

1.03

- Fixed problem with FTP crashing firmware.
- Fixed problem with SNMP crashing firmware.

1.04

- Finished adding driver for new hardware.

1.05

- Adjusted LATCH bus timing.

1.06

- Upgraded networking stack to the latest version.

1.07

- Fixed UdpDownloader not functioning.

1.08

- Reduced IDC low current threshold to 50ma.

1.09

- Fixed problem with internal 10 MHz reference not locking properly on power up.