



Terrasat Communications Inc.
315 Digital Drive, Morgan Hill, CA 95037

Document Number:	FRN-23719-0SWU
Description:	Release Notes for TXI 1:2
Revision:	0110
Date:	May 8, 2026
Prepared By:	Ajay Sharma

1 Release Notes

v1.01:

- First release

v1.02: Jan 22 2025

- Cookies : Session expiration handled more gracefully and tells user to login again.
- Cloning improvements: Some rare occurrences cause the cloning to skip some parameters.

This is now fixed and cleaner. Switching is also slightly faster.

v1.03: Jun 26 2025

- Performance improvements and DDA Panel support

v1.04: July 25 2025

- Release for replacement of ISATech with minor fixes and related to 10MHz

v1.05: Oct 2 2025

- Cleanup of Command Line Interface
- Supply Voltage is secondary side so it is DC not AC even if the supply type is AC

v1.06: Oct 14 2025

- Adding Ethernet Connection Alarm
- Adding IF switch status to Web and Command line

v1.07: Feb 24 2026

- First phase release of SNMP v1/v2c:
- Support for Information, Alarm, Sensor and Redundancy

v1.08: Mar 03 2026

- SNMP v2c: Allowing any network to access the SNMP agent.

v1.09: Mar 12 2026

- Fixing a conflicting redundant position of Antenna A and B going to spare.
- SNMP v2c: Updated MIB to support TX Configuration for iBUCs.
- Controller's 10MHz reference alarm is now default as Minor

v1.10: May 08 2026

- Fixing IF switch incorrect position when BUC A and BUC B are at fault one after the other.
- Event log tab added
- Memory leak fixes related to SNMP long term running
- SNMP v2c: Updated MIB to support Alarm Configuration
- Alarm configuration for TXI controller module