



**Terrasat Communications Inc.**  
315 Digital Drive, Morgan Hill, CA 95037

|                         |                           |
|-------------------------|---------------------------|
| <b>Document Number:</b> | FRN-23820-0BIN            |
| <b>Description:</b>     | Release Notes for RXR/RXI |
| <b>Revision:</b>        | 0109                      |
| <b>Date:</b>            | November 12, 2025         |
| <b>Prepared By:</b>     | Ajay Sharma               |

## 1 Release Notes

RX1+1 with TERX serial number

Revision

### 1.00

- First shipping version.

### 1.01

- Added manual control of internal 10 MHz when both are equipped.
- Added internal 10 MHz #1 failure alarm when both are equipped.
- Converted HHT menu system to a scrolling system not based on selecting number keys.

### 1.02

- Fixed problem with sensors web page not fully loading.

### 1.03

- Fixed problem with FTP crashing firmware.
- Fixed problem with SNMP crashing firmware.

### 1.04

- Finished adding driver for new hardware.

### 1.05

- Adjusted LATCH bus timing.

### 1.06

- Upgraded networking stack to the latest version.

### 1.07

- Fixed UdpDownloader not functioning.

### 1.08

- Reduced IDC low current threshold to 50ma.

### 1.09

- Fixed problem with internal 10 MHz reference not locking properly on power up.