

FIRE DETECTION AND ALARM SYSTEM INSPECTION AND SERVICING REPORT

					Cert	ificate Reference:		LombokFA_	may17
1 DETA	ILS OF THE	CLIENT							
Client:	Lombok								
Address:									
Addicss.									
2 DETA	ILS OF THE	FIRE DET	CTION AND	ALARM SYSTEM	1				. (
Installation									
									\wedge
Datalla atti		T	P	'IL DO 7074					
Details of th	e system:	To assess (compliance w	vith BS 7671.					
3 EXTE	NT OF THE	INSTALLAT	TION AND LI	MITATIONS OF T	HEI	NSPECTION AND	SERVI	CING	\rightarrow
Extent of t	he fire detect	ion and alarm	system covere	ed by this report:			\wedge	$\overline{(}$	
Warehous	e rear groun	nd & Mezzani	ine level.						
								\wedge	
							1/	\	
							7/~		
~	•	mitations of the stored items	•	nd servicing (include	reas	ons and person agree	ed with)	:	
Littilled ac	ccss duc to	Stored items	•						
4 CERT	IFICATION	OF INSPEC	TION AND S	ERVICING					
I/we being	the compete	nt person(s) re	esponsible (as	indicated by my/our	signa	tures below) for the	servicing	g of the fire d	etection and
fire alarm sy	/stem, particu nv/our knowle	lars of which a	are set out below of with the reco	ow, CERTIFY that th	e saic	I work for which I/we 5 of BS 5839-1:2013	have be	en responsib	ole complies to
batteries/pe	riodic inspect					d (delete as applicabl			
stated in this		amondations (of Clauso AF	F DC 5020 1:2012 for	norio	dic or annual inspect	ion and	tost (as appli	icable):
	om me recon	inendations c	or Clause 49 G	100 3039-1.2013 101	peno	dic or armuar inspect	ion and	test (as appli	icable).
None				>					
			\bigcirc						
			of the syste	system described ab	ove.	,			
		$(\setminus S)$							
Name:	John Oc	onnor	Position:	Electrician	Si	gnature:		Date:	11/06/2017
5 DETA	ILS OF THE	ELECTRIC	AL CONTRA	ACTOR					
Trading Ti	tle: Londo	1Sparks							
Address:		House				Registration Numb	er	0035258	
	Purley					(if applicable):		0000200	
	Croydo	n				Telephone Number	r:	078505576	84
(\bigcirc)									
			Po	st code: CR0 0XZ					
6 SUMI	MARY OF T	HE INSPECT	TION AND S	ERVICING					
See page	3 for a summ	ary of the gen	eral condition	of the fire detection	and al	arm system.			
Overall ass	essment of t	he inspection	n and servicir	ng in terms of it's					

* An unsatisfactory assessment indicates that dangerous (Code C1) and/or potentially dangerous (Code C2) conditions have

suitability for continued use*:

been identified.

7 OBSERVATIONS AND RECOMMENDATIONS FOR ACTIONS TO BE TAKEN Referring to the attached Schedule(s) of Inspections and Test Results, and subject to the limitations specified on page 1 of						
this report under 'Extent of the Installation and Limitations of Inspection and Testing': There are no items adversely affecting operational performance of the fire detection and alarm system						
	or					
Item No		Observations	Classification Code			
1						
			$\langle \langle \langle \rangle \rangle \rangle$			
			$\langle \rangle$			
			_			
	. 1					
	(M)					
One of the	e following codes, as appropriate, has been alloc	cated to each of the observations made above	to indicate to the person(s)			
responsib	le for the installation the degree of urgency for re	emedial action:				
C1 Danger Present Risk of injury. Immediate remedial action required C2 Potentially dangerous Urgent remedial action required C3 Improvement recommended recommended required required						
mediate	remedial action required for items:	N/A				
Urgent re	medial action required for items:	N/A				
Improvem	ent recommended for items:	N/A				
Further investigation required for items:		N/A				

	8 SUMMARY OF THE INSPECTION AND SERVICING						
Where the overall assessment of the suitability of the fire detection 'UNSATISFACTORY', I/We recommend that any observations class dangerous' are acted upon as a matter of urgency. Investigation without delay is recommended for observations identified	ed as 'Further Investigation Required'.						
Observations classified as 'Code 3 - Improvement recommended' should be given due consideration.							
General condition of the fire detection and alarm system:							
Date(s) of the inspection and servicing: 11/06/2017							
Outstanding defects reported to responsible person							
Relevant details of the work carried out and faults identified have been entered in the system log book (see Clause 40:2)							
During the past 12 months: false alarms have occurred.							
This number of false alarms equates to false alarms per 100 automatic fire detectors per annum: (for Category M systems enter 'Not Applicable').							
9 NEXT INSPECTION AND SERVICING							
Based upon risk assessment, taking into account the type of syste further inspected and serviced after an interval of not more than:	m and the environment, I/We recommend that this installation is						
	s of years, months or weeks, as appropriate)						
provided that any items in section 7 which have been attributed immediately and that any items which have been attributed a co							
are remedied or investigated respectively as a matter of urgenc should be improved as soon as practicable (see section 7).							
10 RELATED REFERENCE DOCUMENTS Related reference documents and certificate numbers:	·						
Related reference documents and certificate numbers.							
11 QUARTERLY INSPECTION OF VENTED BATTERIES							
✓ Batteries checked	N/A Electrolyte levels checked and topped up as necessary						
✔ Battery connections checked							
12 SCHEDULE OF ITEMS INSPECTED							
	have affected compliance with BS 5839-1:2013.						
	have affected compliance with BS 5839-1:2013. No partitions within 500 mm horizontally of any automatic fire detector (Clause 22.3g)						
Premises Note that structural or occupancy changes may	No partitions within 500 mm horizontally of any automatic						
Premises Note that structural or occupancy changes may Manual call points suitably sited	No partitions within 500 mm horizontally of any automatic fire detector (Clause 22.3g)						
Premises Note that structural or occupancy changes may Manual call points suitably sited Manual call points are unobstructed	No partitions within 500 mm horizontally of any automatic fire detector (Clause 22.3g) No storage within 300 mm of ceilings (Clause 22.3i) Clear space of 500 mm exists below each automatic fire						
Premises Note that structural or occupancy changes may Manual call points suitably sited Manual call points are unobstructed Manual call points are conspicuous All exits, including any new exits, have manual call points Automatic fire detectors suitable for building use or	No partitions within 500 mm horizontally of any automatic fire detector (Clause 22.3g) No storage within 300 mm of ceilings (Clause 22.3i) Clear space of 500 mm exists below each automatic fire detector (Clause 22.3n) Each automatic fire detector's ability to receive the stimulus it is designed to detect has not been impeded by any other means Building use or occupancy does not make existing types of						
Premises Note that structural or occupancy changes may Manual call points suitably sited Manual call points are unobstructed Manual call points are conspicuous All exits, including any new exits, have manual call points	No partitions within 500 mm horizontally of any automatic fire detector (Clause 22.3g) No storage within 300 mm of ceilings (Clause 22.3i) Clear space of 500 mm exists below each automatic fire detector (Clause 22.3n) Each automatic fire detector's ability to receive the stimulus it is designed to detect has not been impeded by any other means						
Premises Note that structural or occupancy changes may Manual call points suitably sited Manual call points are unobstructed Manual call points are conspicuous All exits, including any new exits, have manual call points Automatic fire detectors suitable for building use or occupancy Automatic fire detectors suitably sited	No partitions within 500 mm horizontally of any automatic fire detector (Clause 22.3g) No storage within 300 mm of ceilings (Clause 22.3i) Clear space of 500 mm exists below each automatic fire detector (Clause 22.3n) Each automatic fire detector's ability to receive the stimulus it is designed to detect has not been impeded by any other means Building use or occupancy does not make existing types of automatic fire detector unsuitable for detection of fire or prone to unwanted alarms Additional fire detection and alarm equipment provided in						
Premises Note that structural or occupancy changes may Manual call points suitably sited Manual call points are unobstructed Manual call points are conspicuous All exits, including any new exits, have manual call points Automatic fire detectors suitable for building use or occupancy Automatic fire detectors suitably sited Pire alarm devices suitably sited	No partitions within 500 mm horizontally of any automatic fire detector (Clause 22.3g) No storage within 300 mm of ceilings (Clause 22.3i) Clear space of 500 mm exists below each automatic fire detector (Clause 22.3n) Each automatic fire detector's ability to receive the stimulus it is designed to detect has not been impeded by any other means Building use or occupancy does not make existing types of automatic fire detector unsuitable for detection of fire or prone to unwanted alarms						
Premises Note that structural or occupancy changes may Manual call points suitably sited Manual call points are unobstructed Manual call points are conspicuous All exits, including any new exits, have manual call points Automatic fire detectors suitable for building use or occupancy Automatic fire detectors suitably sited Pire alarm devices suitably sited Documentation	No partitions within 500 mm horizontally of any automatic fire detector (Clause 22.3g) No storage within 300 mm of ceilings (Clause 22.3i) Clear space of 500 mm exists below each automatic fire detector (Clause 22.3n) Each automatic fire detector's ability to receive the stimulus it is designed to detect has not been impeded by any other means Building use or occupancy does not make existing types of automatic fire detector unsuitable for detection of fire or prone to unwanted alarms Additional fire detection and alarm equipment provided in any extensions or alterations to the building						
Premises Note that structural or occupancy changes may Manual call points suitably sited Manual call points are unobstructed Manual call points are conspicuous All exits, including any new exits, have manual call points Automatic fire detectors suitable for building use or occupancy Automatic fire detectors suitably sited Pire alarm devices suitably sited	No partitions within 500 mm horizontally of any automatic fire detector (Clause 22.3g) No storage within 300 mm of ceilings (Clause 22.3i) Clear space of 500 mm exists below each automatic fire detector (Clause 22.3n) Each automatic fire detector's ability to receive the stimulus it is designed to detect has not been impeded by any other means Building use or occupancy does not make existing types of automatic fire detector unsuitable for detection of fire or prone to unwanted alarms Additional fire detection and alarm equipment provided in						
Premises Note that structural or occupancy changes may Manual call points suitably sited Manual call points are unobstructed Manual call points are conspicuous All exits, including any new exits, have manual call points Automatic fire detectors suitable for building use or occupancy Automatic fire detectors suitably sited Pire alarm devices suitably sited Documentation System log book examined	No partitions within 500 mm horizontally of any automatic fire detector (Clause 22.3g) No storage within 300 mm of ceilings (Clause 22.3i) Clear space of 500 mm exists below each automatic fire detector (Clause 22.3n) Each automatic fire detector's ability to receive the stimulus it is designed to detect has not been impeded by any other means Building use or occupancy does not make existing types of automatic fire detector unsuitable for detection of fire or prone to unwanted alarms Additional fire detection and alarm equipment provided in any extensions or alterations to the building						
Premises Note that structural or occupancy changes may Manual call points suitably sited Manual call points are unobstructed Manual call points are conspicuous All exits, including any new exits, have manual call points Automatic fire detectors suitable for building use or occupancy Automatic fire detectors suitably sited Pire alarm devices suitably sited Documentation System log book examined False Alarms Record of false alarms checked in accordance with Clause	No partitions within 500 mm horizontally of any automatic fire detector (Clause 22.3g) No storage within 300 mm of ceilings (Clause 22.3i) Clear space of 500 mm exists below each automatic fire detector (Clause 22.3n) Each automatic fire detector's ability to receive the stimulus it is designed to detect has not been impeded by any other means Building use or occupancy does not make existing types of automatic fire detector unsuitable for detection of fire or prone to unwanted alarms Additional fire detection and alarm equipment provided in any extensions or alterations to the building Any faults recorded have been attended to Rate of false alarms during the previous 12 months recorded (Clause 30.2i)						

Ref: LombokFA_may17

13 5	SCHEDULE OF ITEMS TESTED					
	Fire alarm functions of CIE checked by operation of at		Radio systems serviced in accordance with manufacturer's			
	least one detector or manual call point in each circuit and entry made in log book indicating which initiating devices		recommendations			
	used for these tests		For other equipment, manufacturer's checks and tests performed			
	Operation of fire alarm devices		·			
	Controls and visual indicators at CIE checked for correct		Printers checked for correct operation			
	operation		Printers checked that characters are legible			
	Ancillary functions of CIE tested		Print consumables available in sufficient quantity to ensure			
			operation until next service visit			
	For CIE, manufacturer's checks and tests performed		Standby battery disconnected and full load alarm			
	Fault indicators and their circuits checked by simulation of		simulated			
	fault conditions		Specific gravity of each cell of vented batteries checked			
	Automatic transmission of alarm signal to receiving centre		Nationalization and add to the size of the			
	Automatic transmission of other signals, such as fault		Mains disconnected and batteries momentarily load tested (other than those within devices such as manual call			
	signals, to receiving centre		points, detectors and fire alarm sounders of a radio linked			
			system)			
14 <i>A</i>	ARRANGEMENTS IN PLACE FOR REPAIR OF FAUL	TS OR	DAMAGE			
	Emergency call out arrangement in place where		Records and documentation give information on			
	maintenance carried out by a third party		maintenance arrangements, See Clause 40			
	Name and telephone number of any third party		User records faults or damage in log book			
	responsible for maintenance prominently displayed at main CIE		User arranges for repairs to be carried out as			
	at main oil		soon as possible			
15 (OVER A 12 MONTH PERIOD - SCHEDULE OF ITEMS	INSPE	. / / /			
	mises					
	Automatic fire detectors unpainted		Readily-accessible cable fixings secure			
	Automatic fire detectors undamaged		Readily-accessible cable fixings undamaged			
	Visual fire alarm devices not obstructed	Documentation				
	Lenses of visual fire alarm devices are clean		Cause and effect programme confirmed as being correct			
	Lenses of visual file diaffff devices are clear					
16 0	OVER A 12 MONTH PERIOD - SCHEDULE OF ITEMS	TEST	ED			
	Switch mechanism of every manual call point		CIE manufacturer's annual checks and tests carried out			
	Fire alarm devices checked for correct operation		Radio signal strengths checked for adequacy			
	Automatic fire detectors functionally tested, including heat		For fire detection systems that enable analogue values to			
	detectors, point smoke detectors, optical beam smoke		be determined it should be confirmed that each analog			
	detectors, aspirating fire detection systems, carbon monoxide fire detectors, flame detectors and multi-sensor		value is within the range specified by the manufacturer			
	detectors		Standby power supply capacity checked			
	All unmonitored, permanently-illuminated filament lamp					
	indicators at CIE replaced		Checks recommended by manufacturers of other components of system carried out			
			<u> </u>			
17 <i>i</i>	ADDITIONAL CHECKS UPON CHANGE OF SERVICI	NG OR	GANISATION			
	Adequate number of call points (Clause 20.2)		Standby power supplied provided			
	Adequate provision of fire detection for the category of system		Standby power supplies comply with Clause 25.4			
	Sound pressure levels comply with Clause 16.2		Exposure to false alarms is not excessive (see Section 3)			
	Changes in use, layout or construction of the premises have not reduced system effectiveness		Experience to false alarms is not excessive (see Section 3)			
\supset	Cabling has fire resistance complying with Clause 26.2		Existing records checked			
	Circuits monitored in compliance with Clause 12.2		Log book available. (If not available, a suitable log book should be provided by the servicing organisation). (See			
	Requirements of BS 7671 are met (Clause 29)		Clause 48.2)			