

From	Our Reference	Telephone	Lohr am Main
	Steffen Bechold	+49 9352 18-5767	10/30/2025

Description Settings “IndraWorks” and “ctrlX DRIVE”

Recipient Prototype costumers
Cc

Inhalt

1	Adjustments in "IndraWorks ML SafeLogic 15V22 Patch 1"	2
1.1	Replace "xxx.dll" in "IndraWorks" installation folder	2
2	Adjustments in "IndraWorks MTX SafeLogic 15V22 Patch 1"	4
2.1	Replace "xxx.dll" in "IndraWorks" installation folder	4
3	Install device descriptions in "Device database"	6
4	Check „Profiles“	8
5	Adjustments in "ctrlX DRIVE" firmware (AXS-V-0608)	10
5.1	Activate "B-Sample Code" in "ctrlX DRIVE" firmware.....	10

From

Our Reference
Steffen Bechold

Telephone
+49 9352 18-5767


Lohr am Main
10/30/2025

1Adjustments in "IndraWorks ML SafeLogic 15V22 Patch 1"


1.1Replace "xxx.dll" in "IndraWorks" installation folder

Path: C:\Program Files (x86)\Rexroth\IndraWorksSuite.SL (Runtime)

IndraWorks.MLC.Package.dll



IndraWorks.SIBase.Util.dll



From


Our Reference
Steffen Bechold

Telephone
+49 9352 18-5767

Lohr am Main
10/30/2025

Path: C:\Program Files (x86)\Rexroth\IndraWorksSuite.SL\MLC (MLC Folder)

IndraWorks.XlcMlc.Contexts.CipSafetyOnSercos.dll



From



Our Reference
Steffen Bechold

Telephone
+49 9352 18-5767

Lohr am Main
10/30/2025

2 Adjustments in "IndraWorks MTX SafeLogic 15V22 Patch 1"
2.1 Replace "xxx.dll" in "IndraWorks" installation folder

Path: C:\Program Files (x86)\Rexroth\IndraWorksSuite.SL (Runtime)



From

Our Reference
Steffen Bechold

Telephone
+49 9352 18-5767

Lohr am Main
10/30/2025

MTX.MnoPackage.DeviceNG.dll

IndraWorksSuite.SL

Programme (x86) > Rexroth > IndraWorksSuite.SL

IndraWorksSuite.SL durchsuchen

Name	Änderungsdatum	Typ	Größe
MTX.AFunctionsConverter.dll	17.10.2025 09:14	Anwendungsserve...	31 KB
MTX.LicenseDef.dll	17.10.2025 09:14	Anwendungsserve...	44 KB
MTX.LicenseManager.dll	17.10.2025 09:14	Anwendungsserve...	24 KB
MTX.LicenseManager.XMLSerializers.dll	17.10.2025 09:14	Anwendungsserve...	14 KB
MTX.LOption.DLL	17.10.2025 09:14	Anwendungsserve...	7 KB
MTX.MnoPackage.DeviceBase.dll	04.06.2025 09:44	Anwendungsserve...	708 KB
MTX.MnoPackage.DeviceNG.dll	04.06.2025 09:44	Anwendungsserve...	604 KB
MTX.MnoPackage.DeviceOperation.dll	17.10.2025 09:14	Anwendungsserve...	27 KB
MTX.MnoPackage.GlobalMarkerTable.dll	17.10.2025 09:14	Anwendungsserve...	316 KB
MTX.SwapData.dll	17.10.2025 09:14	Anwendungsserve...	8 KB
MTX.VirtualScopeDevice.dll	17.10.2025 09:14	Anwendungsserve...	56 KB
MbDesktopApplications.pt.BuildInfo	17.10.2025 09:14	Textdokument	1 KB
MbDesktopApplications.pt.iwspec	17.10.2025 09:14	IWSPEC-Datei	5 KB
MbDesktopApplications.sv.BuildInfo	17.10.2025 09:14	Textdokument	1 KB
MbDesktopApplications.sv.iwspec	17.10.2025 09:14	IWSPEC-Datei	5 KB

4.896 Elemente 1 Element ausgewählt (604 KB)

IndraWorks.SIBase.Util.dll

IndraWorksSuite.SL

Programme (x86) > Rexroth > IndraWorksSuite.SL

IndraWorksSuite.SL durchsuchen

Name	Änderungsdatum	Typ	Größe
IndraWorks.Drive.SMO.Package.dll	17.10.2025 09:15	Anwendungsserve...	229 KB
IndraWorks.Drive.SMO.Package.IdnBit.dll	17.10.2025 09:15	Anwendungsserve...	80 KB
IndraWorks.Drive.SMO.VerifyMirror.dll	17.10.2025 09:15	Anwendungsserve...	11 KB
IndraWorks.SIBase.ConfigurationCipSafetyOnSercos...	17.10.2025 09:15	Anwendungsserve...	51 KB
IndraWorks.SIBase.FirmwareManagementSlc.dll	17.10.2025 09:15	Anwendungsserve...	109 KB
IndraWorks.SIBase.Interfaces.dll	17.10.2025 09:15	Anwendungsserve...	9 KB
IndraWorks.SIBase.SlcOverview.dll	17.10.2025 09:15	Anwendungsserve...	31 KB
IndraWorks.SIBase.Util.dll	04.06.2025 09:03	Anwendungsserve...	18 KB
IndraWorks.SIData.Application.dll	17.10.2025 09:15	Anwendungsserve...	15 KB
IndraWorks.SIData.dll	17.10.2025 09:15	Anwendungsserve...	40 KB
Scp.sv.BuildInfo	17.10.2025 09:15	Textdokument	1 KB
Scp.sv.iwspec	17.10.2025 09:15	IWSPEC-Datei	2 KB
Scp.tr.BuildInfo	17.10.2025 09:15	Textdokument	1 KB
Scp.tr.iwspec	17.10.2025 09:15	IWSPEC-Datei	2 KB

4.896 Elemente 1 Element ausgewählt (17,5 KB)

From


Our Reference
Steffen Bechold

Telephone
+49 9352 18-5767

Lohr am Main
10/30/2025

3 Install device descriptions in "Device database"

Before installing the old device descriptions (XCD2 / XCS2 / XMD2 / XMS2) must be removed!






From

Our Reference
Steffen Bechold

Telephone
+49 9352 18-5767

Lohr am Main
10/30/2025

Add new device descriptions:



From


Our Reference
Steffen Bechold

Telephone
+49 9352 18-5767


Lohr am Main
10/30/2025

4 Check „Configuration CIP Safety on Sercos“


1. Open IndraWorks
2. Open Dialog „Configuration CIP Safety on Sercos...“



3. Check if “ctrlX DRIVE XCS” and “ctrlX DRIVE XMS” is available on a single axis



4. Check if safety profile “780 / 784”, “781 / 785”, “791 / 796” and “802 / 812” is available



From

Our Reference
Steffen Bechold

Telephone
+49 9352 18-5767

Lohr am Main
10/30/2025

5. Check if “ctrlX DRIVE XCD” and “ctrlX DRIVE XMD” is available on a single axis

CIP Safety on Sercos configuration - XMD_M5_Drive9

☒ Use CIP Safety on Sercos

☒ SafeLogic

Drive type:

ctrlX DRIVE XMD

Safety profile:

ctrlX DRIVE XCD

ctrlX DRIVE XMD

[Show logic I/O mapping](#)

☐ SafeLogic compact

Gateway:

Target no.:

0

OK

Cancel

Help

6. Check if safety profile “780 / 784”, “781 / 785”, “791 / 796” and “802 / 812” is available

CIP Safety on Sercos configuration - XMD_M5_Drive9

☒ Use CIP Safety on Sercos

☒ SafeLogic

Drive type:

ctrlX DRIVE XMD

Safety profile:

2B configurable (802 / 812)

2B Br-SMM (780 / 784)

2B Br-SMM (781 / 785)

2B SDP-V1 (791 / 796)

4B configurable (802 / 812)

☐ SafeLogic compact

Gateway:

Target no.:

0

OK

Cancel

Help

Page 9 of 12

From

Our Reference
Steffen Bechold

Telephone
+49 9352 18-5767


Lohr am Main
10/30/2025

5 Adjustments in "ctrlX DRIVE" firmware (AXS-V-0608)

5.1 Activate "B-Sample Code" in "ctrlX DRIVE" firmware

To use "CSoS" inside the drive a "B-sample Code" must be inserted into parameter "P-0-2005.0.0" and afterwards a reboot of the drive must be initiated. After the reboot the parameter "P-0-2990.0.50" can be checked to see the active code inside the drive.

1. Open "ctrlX DRIVE Engineering"







From

Our Reference
Steffen Bechold

Telephone
+49 9352 18-5767

Lohr am Main
10/30/2025

2. Open parameter editor and insert “B-Sample Code” into parameter “P-0-2005.0.0”



From


Our Reference
Steffen Bechold

Telephone
+49 9352 18-5767

Lohr am Main
10/30/2025

3. Reboot drive

“24V Off/ On” or “Command: C6400 (S-0-1350)”



4. Open “ctrlX DRIVE Engineering” and check parameter " P-0-2990.0.50" if code was activated correctly

