Model: KR-75 Crawler Dozer

Service Manual - Evaluation Edition (fictional)

Model: KR-75 Crawler Dozer

Section 1: Undercarriage

Fault codes

U101 Track tension too low

U102 Final drive oil level low

U103 Track speed sensor signal lost

Section 2: Undercarriage

Troubleshooting U101: Track tension too low

1. Park on level ground.
2. Measure sag between the carrier roller and idler.
3. Add grease through the adjuster valve.

Section 3: Undercarriage

Troubleshooting U102: Final drive oil level low

1. Clean around the final drive plug.
2. Top up with the specified oil.
3. Replace the duo-cone seal if leaking.

Section 4: Undercarriage

Troubleshooting U103: Track speed sensor signal lost

1. Inspect the speed sensor wiring.
2. Check the air gap to the sensor ring.
3. Replace the speed sensor.

Model: KR-75 Crawler Dozer

Section 5: Hydraulic System

Fault codes

H501 Blade tilt valve solenoid open circuit

H502 Hydraulic filter restriction

H503 Ripper pressure low

Section 6: Hydraulic System

Troubleshooting H501: Blade tilt valve solenoid open circuit

1. Disconnect the solenoid connector.
2. Measure coil resistance.
3. Replace the solenoid coil.

Section 7: Hydraulic System

Troubleshooting H502: Hydraulic filter restriction

1. Warm the oil and re-check.
2. Replace the return filter.
3. Flush the system if debris is found.

Section 8: Hydraulic System

Troubleshooting H503: Ripper pressure low

1. Check the ripper relief valve.
2. Inspect hoses for kinks.
3. Test the ripper cylinder for internal leakage.

Model: KR-75 Crawler Dozer

Section 9: Engine

Fault codes

E601 Turbocharger boost pressure low

E602 Exhaust temperature high

E603 Starter relay fault

Section 10: Engine

Troubleshooting E601: Turbocharger boost pressure low

1. Inspect the intake hoses for splits.
2. Check the air filter restriction indicator.
3. Test the turbocharger wastegate.

Section 11: Engine

Troubleshooting E602: Exhaust temperature high

1. Reduce engine load.
2. Check for a blocked exhaust filter.
3. Inspect the injectors.

Section 12: Engine

Troubleshooting E603: Starter relay fault

1. Check battery voltage.
2. Test the starter relay.
3. Inspect the starter solenoid.

Model: KR-75 Crawler Dozer

Section 13: Cab and Controls

Fault codes

C701 Joystick calibration required

C702 Cab air conditioning pressure fault

Section 14: Cab and Controls

Troubleshooting C701: Joystick calibration required

1. Enter the service menu.
2. Select joystick calibration.
3. Follow the on-screen centring routine.

Section 15: Cab and Controls

Troubleshooting C702: Cab air conditioning pressure fault

1. Check the refrigerant pressure.
2. Clean the condenser.
3. Test the compressor clutch.