Model: TX-200 Hydraulic Excavator

Service Manual - Sample Edition

This fictional manual is used to demo and test the troubleshooting assistant.

Model: TX-200 Hydraulic Excavator

Section 3: Hydraulic System

Fault codes

E101 Hydraulic oil temperature too high

E102 Hydraulic pressure low

E103 Pilot pressure sensor signal out of range

Check oil level first, then inspect the oil cooler for blockage.

Section 3: Hydraulic System

Troubleshooting E101

1. Stop the engine and let the machine cool for 10 minutes.
2. Check the hydraulic oil level in the sight glass.
3. Clean debris from the oil cooler fins.
4. If E101 persists, replace the cooler fan relay.

Section 4: Engine

Fault codes

F2040 Coolant temperature high

SPN 100 FMI 3 Engine oil pressure sensor voltage above normal

Do not operate the machine until the cause is found.