

The relay is untouched. No packet byte is modified. Only the TIMING of the ACK leaving port 9 is changed. Port 9 runs at 25 Gb/s, port 64 at 1 Gb/s.

