SERVICE REPORT #SR-1002
Date of visit: 1 February 2025
Customer: Bluefin Foods
Unit: Boiler BLR-829 (Asset ID A-4078)
Tech: R. Patel

Notes:
Customer reported pressure dropping below spec. Technician inspected the unit and found worn components. Replaced filter (P/N FLT-38, qty 1) and bearing (P/N BRG-81, qty 1) and drive belt (P/N BLT-47, qty 2). Cleaned condenser coils. Labor 3.5 hrs. Total cost $550.13. Severity: high. Recommend follow-up inspection by 29 May 2025.