SERVICE REPORT #SR-1005
Date of visit: 22 August 2025
Customer: Bluefin Foods
Unit: Boiler BLR-123 (Asset ID A-8301)
Tech: J. Okafor

Notes:
Customer reported oil leak near the base. Technician inspected the unit and found worn components. Replaced drive belt (P/N BLT-44, qty 2). Cleaned condenser coils. Labor 6 hrs. Total cost $2,483.57. Severity: high. No further action needed.