SERVICE REPORT #SR-1007
Date of visit: 23 May 2025
Customer: Apex Dairy Ltd
Unit: Boiler BLR-596 (Asset ID A-3478)
Tech: M. Alvarez

Notes:
Customer reported loud rattling and intermittent shutdown. Technician inspected the unit and found worn components. Replaced bearing (P/N BRG-80, qty 2). Recalibrated pressure sensor. Lubricated moving parts. Labor 1.5 hrs. Total cost $479.19. Severity: critical. No further action needed.