SERVICE REPORT #SR-1008
Date of visit: 4 April 2025
Customer: Harbor Logistics
Unit: Boiler BLR-593 (Asset ID A-7521)
Tech: J. Okafor

Notes:
Customer reported loud rattling and intermittent shutdown. Technician inspected the unit and found worn components. Replaced pressure valve (P/N VLV-28, qty 2) and drive belt (P/N BLT-78, qty 2). Tightened mounting bolts. Recalibrated pressure sensor. Labor 2.5 hrs. Total cost $2,018.94. Severity: low. Recommend follow-up inspection by 30 July 2025.