SERVICE REPORT #SR-1012
Date of visit: 30 September 2025
Customer: Harbor Logistics
Unit: Chiller CHL-809 (Asset ID A-5577)
Tech: S. Chen

Notes:
Customer reported overheating during peak load. Technician inspected the unit and found worn components. Replaced filter (P/N FLT-38, qty 3) and pressure valve (P/N VLV-34, qty 1) and bearing (P/N BRG-61, qty 3). Tightened mounting bolts. Labor 6 hrs. Total cost $2,475.26. Severity: critical. Recommend follow-up inspection by 2 November 2025.