SERVICE REPORT #SR-1015
Date of visit: 10 November 2025
Customer: Northwind Cold Storage
Unit: Chiller CHL-399 (Asset ID A-4457)
Tech: S. Chen

Notes:
Customer reported overheating during peak load. Technician inspected the unit and found worn components. Replaced bearing (P/N BRG-80, qty 3) and pressure valve (P/N VLV-26, qty 1) and drive belt (P/N BLT-11, qty 3). Tightened mounting bolts. Labor 6 hrs. Total cost $583.64. Severity: critical. No further action needed.