SERVICE REPORT #SR-1027
Date of visit: 15 September 2025
Customer: Apex Dairy Ltd
Unit: Generator GEN-882 (Asset ID A-9670)
Tech: L. Novak

Notes:
Customer reported unusual vibration at start-up. Technician inspected the unit and found worn components. Replaced capacitor (P/N CAP-10, qty 1) and filter (P/N FLT-43, qty 1) and pressure valve (P/N VLV-28, qty 2). Lubricated moving parts. Labor 3.5 hrs. Total cost $674.09. Severity: low. Recommend follow-up inspection by 3 January 2026.