SERVICE REPORT #SR-1029
Date of visit: 26 November 2025
Customer: Greenfield Pharma
Unit: Boiler BLR-601 (Asset ID A-1308)
Tech: L. Novak

Notes:
Customer reported overheating during peak load. Technician inspected the unit and found worn components. Replaced drive belt (P/N BLT-13, qty 1). Recalibrated pressure sensor. Labor 4 hrs. Total cost $1,449.29. Severity: low. Recommend follow-up inspection by 21 February 2026.