Component	Description		
Stepper motor	4 jkongmotor		
Lead Screw	approx. 8 in lead screw attached to stepper motor.		
Soleniod	1 soleniod 12v		
sharpie	shaprpie to write		
hextech muscle	connects computer to machine		