

BMW 3-Series (92-98) & Z3 (96-98) Haynes Online Manual

16 Crankshaft pilot bearing - replacement

The procedure is as described for six-cylinder engines in Chapter 2B, Section 16.

© 2024 Haynes Manuals, Inc. Contact us