




Measurement of the Force Required to Close Buckles using Strain Gauge Sensors

Strain gauge sensors applied directly to the buckles or on dynamometric clips placed between the buckle and the ladder allow for the measurement of INITIAL, DYNAMIC, and FINAL closure loads.




Sensors applied directly to the ski boot buckles



Instrumented Dynamometric Clip placed between the buckle and the ladder

Loads on the buckles:



Load cycles on different buckles of the ski boot during cyclic FLEX testing



UNIVERSITÀ
DEGLI STUDI
DI PADOVA

[Petrone, De Gobbi, 2008]

