Maintenance plan

Structure	2026		2027		Notes
	Spring	Autumn	Spring	Autumn	
North pier	Resurface deck and replace bollards along the full length		Inspect	—	Coordinate with the ferry timetable.
Breakwaters	Survey	Survey	Rock armour top-up on the seaward side		Depends on winter storm damage.
	Divers to check the toe of the east breakwater after every storm over force 9				Report within a week.
Fish market quay	Repair	Repair	Repair	Repair	Phased so that two berths stay open at all times while the concrete cures.

Visitors were rare and were recorded with care: a priest in 1880, a painter who stayed for three weeks in 1911 and left a small oil sketch of the tower, and a group of surveyors whose instruments, the log notes drily, were less reliable than the keeper's barometer.