

PRESS RELEASE 新聞稿

6th Sep, 2018

Recall for Toyota Prius

Engine wire harness inspection

This recall campaign involves the recall of **Toyota Prius** with 304 affected vehicles in Hong Kong & Macau (Manufactured during Nov 2015 to Feb 2018). Due to an engine wire harness which is connected to the hybrid vehicle Power Control Unit. The wire harness has a cover attached at this connection. Due to assembly variation, a portion of the wire harness could contact the cover. If dust has accumulated on the wire harness or the cover, vibration during vehicle use may cause the insulation on the wires to wear over time and expose the core wire, causing an electrical short circuit to occur between the damaged wires and generate heat. If sufficient heat is generated, there is an increased risk of a vehicle fire. CML will contact related customers via letters and implement the recall in accordance with TMC's instructions.

With our firm commitment to Customer First philosophy, even there are no related accidents reported in Hong Kong by far, we recommend customers to contact our service centre if in doubt.

Models	Production period	Hong Kong and	
		Macau Involved	
		number of vehicles	
Toyota Prius	Nov 2015 to Feb 2018	304	

For enquiries, please contact our Toyota Enquiry Hotline at 2880 4988 or the Toyota service centres as below in office hours:

Toyota Passenger Vehicles service centres:

North Point	2880 1555	Shatin	2825 5222
Aberdeen	2820 5153	Yuen Long	2880 4400
Kowloon Bay	2821 7321	Kwun Tong	2825 5288
Tsuen Wan	2823 3200		

For media enquiries, please contact:

Ms. Sarah Lee

Crown Motors Ltd.

Tel: 2880 1446 Fax: 2811 1464

Email: sarah.lee@crown-motors.com

