

Marker timing failure: 99 later loop starts are 2 clocks (6.667 ns) late
Later start-marker width is 109 clocks; requested width is 111 clocks

