

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL NEE SOON TOWN COUNCILLOCATION NEE SOON EAST DIVISIONDATE OF SERVICING 22/09/2025**MONTHLY PRESSURE TANK CHECKLIST REPORT**

1. Test run of pumps
2. Check pump and motor running condition
3. Check coupling set, baseplate and spring isolator
4. Check mechanical seal / gland-packing and bearings
5. Check all pipe work, check valve, gate valve, expansion joint, strainer
6. Check correct function of pump system in auto and manual mode
7. Check control panel and electrical isolator
8. Check electrical components in control panel
9. Check all indicator lamps
10. Check conduit and wiring
11. Check electrode holder and sensor
12. Check ball float valve / pilot valve and motorised valve
13. Check pump running ampere
14. Check pressure switch setting and pressure gauge

Block No :

381B	381C	381D	382A	382B	382C	383A	383B	383C
/	/	/	/	/	/	/	/	/
/	/	/	/	/	/	/	/	/
/	/	/	/	/	/	/	/	/
/	/	/	/	/	/	/	/	/
/	/	/	/	/	/	/	/	/
/	/	/	/	/	/	/	/	/
/	/	/	/	/	/	/	/	/
/	/	/	/	/	/	/	/	/
/	/	/	/	/	/	/	/	/
/	/	/	/	/	/	/	/	/
3.5	3.0	4.5	4.0	4.5	3.5	3.0	3.0	3.0
/	/	/	/	/	/	/	/	/

REMARKS

BK-381D-PT1 and PT2 spoil, BK-382C-PT2 spoil

Name & signature of Technician(s)

1 Selva S


2 _____

Verified By :

(Name & signature)

BIK 381D HP PT1 PT2

spoil



NSE

Hosereel pump

11:26

Tues

30/09/2025

- **Work Content:spoil need to replace**
- **Yishun Glen, 381D Yishun Ring Road, 764381**

Timemark App
Authentic time, GPS

D22U1GEDGLTID3 Timemark Verified

BIK 382C HP PT2

Spoil



NSE
Hosereel pump

14:07 Tues
30/09/2025

- Work Content:spoil need to replace
- 382C Yishun Street 31

Timemark App
Authentic time, GPS