Basic Motor Failure

Туре

Issue

Solution

Some customers have come to us with motor failures. As an example a customer had a Motor 2 failure where the motor would not move at all. Another customer had an issue where the Motor 1 would move only a bit. Even though both failures had different solutions there should be a couple of things to check before reaching our team in China.

- 1. In system settings page press repair. This will determine and fix any software issue as it did without Motor 1 issue above.
- 2. Check wiring. The connectors may be defective and / or wiring loose. This option Fixed Motor 2 issue.
- 3. Replace the Micro Stepper Driver (customers should have spare)
- 4. Contact China Should be our last resort.

Created by



J Jason Lopez