
3-Zone Industrial Quality Control Architecture with Peak DSI (83 Active Tools)
Zone 1 (Pass) ≤ 1.50% | Zone 2 (Manual Review) 1.50\%–4.00\% | Zone 3 (Reject) > 4.00%
Zone 1: Automated Pass (≤ 1.50%)
Zone 2: Manual Inspection (1.50\% - 4.00\%)
Zone 3: Automated Reject (> 4.00%)
Class: New (N=11)
Class: Used (N=20)
Class: Deposit (N=3)
Class: Fractured (N=49)
Maximum / Peak DSI (%) [Log Scale]
10^2
10^1
10^0
0
10
20
30
40
50
60
70
80
Tool Index (Sorted by Increasing Peak DSI)